Shenandoah Community School District Board of Directors November 2, 2020 – 5:00 p.m. Zoom Meeting ID: 892 2870 8448 Passcode: QU0tee

Board Agenda

- 1. Call to Order
- 2. Roll Call and Determination of Quorum
- 3. Action Items
 - a. Approve Substantial Completion Documents for Signature
 - i. Genesis Contracting Group Bid Package 1 & 2
 - ii. Rasmussen Mechanical Services Bid Package 3
 - iii. Control Management Bid Package 4
 - iv. Big Sky Enterprises (K2 Electric) Bid Package 5
 - v. Tri-City Electric Company Bid Package 6
 - vi. McGill Asbestos Bid Package 7 & Phase 2
 - vii. Genesis Contracting Group Bid Package 8
- 4. Adjournment

Work Session – No Pending Action Zoom Meeting ID: 828 2507 1724 Passcode: UUHH4x

Board Agenda

- 1. Call to Order
- 2. Roll Call and Determination of Quorum
- 3. Discussion Items:
 - a. Board Goals
- 4. Informational Items
 - a. Next Regular Meeting –November 9, 2020 at 5:00 p.m.
- 5. Adjournment

AIA° Document G704/CMa° – 1992

Certificate of Substantial Completion Construction Manager-Adviser Edition

PROJECT:

(Name and address) Shenandoah HS Renovations and Addition

TO OWNER: (Name and address) Shenandoah Community School District 304 W Nishna Road Shenandoah, Iowa, 51601

PROJECT NUMBER: 11-16116-20/ **CONTRACT FOR:** General Construction CONTRACT DATE: March 9, 2020

TO CONTRACTOR: (Name and address) Genesis Contracting Group, LLC 404 Hill Street Lincoln, NE 68502

OWNER: X CONSTRUCTION MANAGER: ARCHITECT: X CONTRACTOR: X FIELD: OTHER:

DATE OF ISSUANCE: September 21, 2020

PROJECT OR DESIGNATED PORTION SHALL INCLUDE:

Bid Package 1 & 2 excluding items for Secure Entrance, Door Access Controls, and Automatic Operators.

The Work performed under this Contract has been reviewed and found, to the Construction Manager's and Architect's best knowledge, information and belief, to be substantially complete. Substantial Completion is the stage in the progress of the Work when the Work or designated portion thereof is sufficiently complete in accordance with the Contract Documents so the Owner can occupy or utilize the Work for its intended use. The date of Substantial Completion of the Project or portion thereof designated above is hereby established as August 26, 2020 which is also the date of commencement of applicable warranties required by the Contract Documents, except as stated below:

Warranty

Date of Commencement

August 26, 2020

A list of items to be completed or corrected is attached hereto. The failure to include any items on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents. 1

| CARL A. NELSON COMPANY | lynt dors | 9/24/2020 |
|---|--|---|
| CONSTRUCTION MANAGER | ВҮ | DATE |
| DLR Group inc. (an Iowa corporation) | Mike Kros | 9/23/2020 |
| ARCHITECT | ВҮ | DATE |
| The Contractor will complete or correct the Completion. Genesis Contracting Group CONTRACTOR | e Work on the list of items attached hereto with BY | thin 23 days from the above date of Substantial 10/21/2020 DATE |
| The Owner accepts the Work or designated on August 26, 2020 (date). | l portion thereof as substantially complete and | 1 will assume full possession thereof $\epsilon~8{:}00~AM$ |
| Shenandoah Community School District | | |
| OWNER | BY | DATE |

AIA Document G704/CMa[™] - 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:48:24 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes: (3B9ADAB5)

(Note--Owner's and Contractor's legal and insurance counsel should determine and review insurance requirements and coverage.)

August 26, 2020

AIA Document G704/CMa[™] - 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:48:24 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes: (3B9ADAB5)

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Phase | Comments |
|--------|-------------------|--------------|----------------|--------------|---|------|-------|--|
| B100 | VESTIBULE | Genesis (GC) | Storefront | Caulking | Caulk around HM and aluminum storefronts | | 1 | Caulking at HM needs paint along head of HM and P1 wall. |
| C118 | GIRLS LOCKER | Genesis (GC) | C118A | Caulking | Sealant added around door frame, inside and out. | | 1 | Caulking done. Caulking at HM needs paint on interior. |
| C126 | TRAINING | Genesis (GC) | | Caulking | Replace caulking with a color matched caulk, or paint carefully as to not get pain on ceramic tile. | | 1 | DLR Item #200 |
| C126 | TRAINING | Genesis (GC) | | Caulking | Caulking on both doors C126 and C126A installation done poorly and needs to be removed and redone . All caulking after installation to be removed off frame | | 1 | DLR Item 194 |
| B119 | FCS | Genesis (GC) | Ceiling | Ceiling Tile | Repair grid and ceiling tile by hood at ADA kitchen | | 1 | |
| 006 | VESTIBULE | Genesis (GC) | | Door | New door hardware/auto operator not installed | | 1 | Wood door not opening fully. |
| B103 | OFFICE | Genesis (GC) | B103 and B103A | Door | Missing kick plates | | 1 | DLR Item 217 |
| B111 | PASSAGE | Genesis (GC) | North | Door | Missing locking cylinder in access panel. | | 1 | |
| C126 | TRAINING | Genesis (GC) | C126 and C126A | Door | Missing kick plates | | 1 | DLR Item #194 |
| C122 | GUEST LOCKER ROOM | Genesis (GC) | | Flooring | Existing floor from Corridor C121 into Boys/Girls Lockers C122 to be filled in or leveled off to prevent tripping hazard | | 1 | DLR Item #198 |
| B100 | VESTIBULE | Genesis (GC) | Storefront | General | New GWB wall, missing wall base. The new HM frames and GWB wall are rated 1-C. The large gap between the two needs to be closed off in order to meet the rating. The metal studs at the jamb will need to be moved into the throat of the HM frame to ensure wall rating, see typical jamb detail 42/A9.1. Currently the jamb of the HM frame appears to be held in place by wood shims, this is unacceptable. The HM frame must be anchored into the jamb of the metal studs. | | 1 | See DLR item #186 |
| B102 | CORRIDOR | Genesis (GC) | | General | Missing break metal trim piece at Secure Entry | | 1 | DLR Item #188 |
| C119 | TOILET | Genesis (GC) | | General | Install mirror (1) | | 1 | Not on-site |
| C124 | TOILET | Genesis (GC) | | General | Install mirror (1) | | 1 | Not on-site |
| C126 | TRAINING | Genesis (GC) | Floor | General | Repair needed so slope of floor to shower drain. DLR to speak to rep to discuss possible solutions. | | 1 | DLR Item #195 |
| C126 | TRAINING | Genesis (GC) | | General | Plastic used to mask off for flooring/ base installation to be removed. Several tiles within shower to have markings, remove. APC grid needs to have grout removed, typical entire room. | | 1 | DLR Item #192 |
| C128 | TOILET | Genesis (GC) | | General | Install mirrors (3) | | 1 | Not on-site |
| C129 | SHOWER | Genesis (GC) | Floor | General | Review slope of floor to shower drain in south shower stall. | | 1 | Ok per plans. DLR to advise. |
| | GENERAL NOTE | Genesis (GC) | Shower stalls | General | Clean construction dust from all showers. Typical in showers in C129, C125, C120. | | 1 | DLR Item #205 |
| | GENERAL NOTE | Genesis (GC) | Shower stalls | General | At all shower partitions shower head rails, vertical gaps must be infilled with trim piece to match to maintain privacy. Typical all showers in C129, C125, C120. | | 1 | DLR Item #196 |

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Phase | Comments |
|--------|------------------------|--------------|------------------|---------|---|------|-------|--|
| | GENERAL NOTE | Genesis (GC) | Shower doors | General | C129, C125, and C120 - Adjust shower doors so they remain open 30 degrees for drying purposes as stated on submittal 102116.19_toilet shower and dressing compartment dated 200521. Typical all doors. | | 1 | DLR Item #213, 214, 215 |
| B102 | CORRIDOR | Genesis (GC) | | Paint | Remove paint at top of wall meets APC grid at Secure Entry. | | 1 | DLR Item #188 |
| C118 | GIRLS LOCKER ROOM | Genesis (GC) | C118A | Paint | Paint door and frame. | | 1 | Door was vandalized. May need to be replaced outside of the project. |
| C119 | TOILET | Genesis (GC) | | Paint | Clean paint off of toilet paper dispenser. | | 1 | DLR Item # 209 |
| C126 | TRAINING | Genesis (GC) | | Paint | CMU to be painted to match adjacent wall and sealant added at tile edge/ CMU. Typical at similar conditions. | | 1 | DLR Item #190, #193 |
| C137 | SAFE ROOM | Genesis (GC) | | Sign | Missing safe room signage | | 1 | GH confirmed |
| | General Notes - Area A | Genesis (GC) | Area B | Sign | Signage not installed | | 1 | Arriving middle of Oct. |
| | General Notes - Area B | Genesis (GC) | Area B | Sign | Signage not installed | | 1 | Arriving middle of Oct. |
| | General Notes - Area C | Genesis (GC) | Area D | Sign | Signage not installed | | 1 | Arriving middle of Oct. |
| | General Notes - Area D | Genesis (GC) | Area C | Sign | Signage not installed | | 1 | Arriving middle of Oct. |
| | Chiller | Genesis (GC) | Chiller | Site | Chiller - provide pea gravel, redo/repair sidewalk, reset fence | | 1 | |
| | Chiller | Genesis (GC) | Chiller | Site | Reinstall downspout extension at chiller | | 1 | Not done on 10/7 |
| | Landscaping | Genesis (GC) | All | Site | Dirt in east islands and at least one of the west islands has settled. More dirt is needed. More river stone needed by Cafeteria entrance. | | 1 | |
| | Paving | Genesis (GC) | Paving | Site | Cut curbs at angle at top of stairs per detail 25/C4.1 | | 1 | Owner confirmed wants this on 10/08 |
| | Paving | Genesis (GC) | Paving | Site | Bevel cut sidewalk control joints | | 1 | 1/2 done |
| | Paving | Genesis (GC) | Paving | Site | Replace concrete pavement on drive east of wrestling room | | 1 | |
| | DOAS | Genesis (GC) | DOAS | Site | Fence around DOAS-1 installation not complete. Construction | | 1 | |
| | Paving | Genesis (GC) | | Site | Tactile pads are not centered in route to auditorium. | | 1 | Owner review |
| | Paving | Genesis (GC) | Curb cuts | Site | Typical at all curb ramps - ensure curbs are properly cut per detail and joints are properly sealed. | | 1 | cut out and repour 5' back |
| | Paving | Genesis (GC) | Stairs and Ramps | Site | Mound grout up 1/4" around post and cover with sealant typical all railings | | 1 | GH confirmed |
| B150 | TOILET | Genesis (GC) | All Walls | Tile | Tile Wall Repair - bug holes and coloration | | 1 | not done 9/30 |

MAIA® Document G704/CMa[®] – 1992

Certificate of Substantial Completion Construction Manager-Adviser Edition

PROJECT:

(Name and address) Shenandoah HS Renovations and Addition

TO OWNER: (*Name and address*) Shenandoah Community School District 304 W Nishna Road Shenandoah, Iowa, 51601 PROJECT NUMBER: 11-16116-20/ CONTRACT FOR: General Construction CONTRACT DATE: March 6, 2020

TO CONTRACTOR: (Name and address) Rasmussen Mechanical Services 3100 Nebraska Avenue Council Bluffs, IA 51501 OWNER: 🗙

ARCHITECT:

CONTRACTOR: X

FIELD:

1

DATE OF ISSUANCE: September 21, 2020

PROJECT OR DESIGNATED PORTION SHALL INCLUDE:

Bid Package 3.

The Work performed under this Contract has been reviewed and found, to the Construction Manager's and Architect's best knowledge, information and belief, to be substantially complete. Substantial Completion is the stage in the progress of the Work when the Work or designated portion thereof is sufficiently complete in accordance with the Contract Documents so the Owner can occupy or utilize the Work for its intended use. The date of Substantial Completion of the Project or portion thereof designated above is hereby established as August 26, 2020 which is also the date of commencement of applicable warranties required by the Contract Documents, except as stated below:

Warranty

Date of Commencement

0/24/2020

August 26, 2020

A list of items to be completed or corrected is attached hereto. The failure to include any items on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

1-1

| CARL A. NELSON COMPANY | uput dars | 9/24/2020 | |
|--|---|--|--------|
| CONSTRUCTION MANAGER | BY | DATE | |
| DLR Group inc. (an Iowa corporation) | Mike Krok | 9/23/2020 | |
| ARCHITECT | BY | DATE | |
| The Contractor will complete or correct th Substantial Completion. | e Work on the list of items attached herete | o within thirty (30) days from the above date of | |
| Rasmussen Mechanical Services | Ala The | 9/28/2020 | |
| CONTRACTOR | BY | DATE | |
| The Owner accepts the Work or designate on August 26, 2020 (date). | d portion thereof as substantially complete | e and will assume full possession thereof at | (time) |
| Shenandoah Community School District | | | |
| OWNER | BY | DATE | |
| | | | |

AIA Document G704/CMaTM – 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:49:12 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes: (3B9ADAB3)

(Note--Owner's and Contractor's legal and insurance counsel should determine and review insurance requirements and coverage.)

August 26, 2020

AIA Document G704/CMaTM - 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:49:12 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes: (3B9ADAB3)

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Phase | Comments |
|--------|--------------------|------------------|----------|------------|---|------|-------|---|
| D107 | BOILER | Rasmussen (Mech) | | Insulation | Insulation at chilled water pumps not complete. Condensation is accumulating on the inside of the fiberglass insulation where the ends are not sealed. | | 1 | SL - Done per feedback from insulator, need to verify. |
| B120 | BIOLOGICAL SCIENCE | Rasmussen (Mech) | | Label | Provide label on push button to EF-2 stating Exhaust Fan. | | 1 | SL - Confirm Done |
| B132 | PHYSICAL SCIENCE | Rasmussen (Mech) | | Label | Provide label on push button to EF-2 stating Exhaust Fan. | | 1 | SL - Confirm Done |
| C126 | TRAINING | Rasmussen (Mech) | Ceiling | Label | Provide pipe labels typical of each restroom. | | 1 | SL - Confirm Done |
| D107 | BOILER | Rasmussen (Mech) | | Label | Finish insulating and labeling hydronic piping in mechanical room. | | 1 | NOT DONE 9/12 |
| B120 | BIOLOGICAL SCIENCE | Rasmussen (Mech) | UV | Mechanical | No hot water circulation in UV-18 | | 1 | SL confirmed done. Bled out the air. |
| B130 | WOMENS | Rasmussen (Mech) | EF | Mechanical | Motor needs replaced in EF-3 | | 1 | Maintence Item - motor bad, will be replaced. |
| C118 | WOMEN'S LOCKER RM | Rasmussen (Mech) | UV | Mechanical | Valves leaking. | | 1 | SL - Confirm Done |
| D107 | BOILER | Rasmussen (Mech) | Boilers | Mechanical | Additional temperature sensors per RFI 72 | | 1 | |
| D107 | BOILER | Rasmussen (Mech) | Boilers | Mechanical | The factory hot water supply sensor that is wired to the master boiler failed | | 1 | From CMI, CMI to confirm done. |
| D107 | BOILER | Rasmussen (Mech) | Boilers | Mechanical | The only values that appear to be bad are the system hot water supply temp at AI-4, Boiler 1 Module 4 hot water supply temp at AI-46 and Boiler 1 Module 4 hot water return temp at AI-47. | | 1 | From CMI, CMI to confirm done. |
| D107 | BOILER | Rasmussen (Mech) | Boilers | Mechanical | No communication between Boiler 2 and BAS. Need to add ModBUS connection for Boiler 2 info. | | 1 | IMEG issue. Needs meeting with boiler rep. on 9/14. Boiler Rep still needs to reset boiler as of 9/17. |
| | GENERAL NOTE | Rasmussen (Mech) | AHU | Mechanical | No hot water flow to AHU 1, 2, 3, 5 and 6 | | 1 | |
| | GENERAL NOTE | Rasmussen (Mech) | AHU | Mechanical | Resheave AHU 7 | | 1 | Change Order - Parts on back order. Expected delivery 9/28 |
| | GENERAL NOTE | Rasmussen (Mech) | AHU | Mechanical | Resheave AHU1, 3, 4, and 5 | | 1 | SL - Confirm Done |
| | GENERAL NOTE | Rasmussen (Mech) | AHU | Mechanical | Replace blower wheel bearing assembly AHU 3, 4, and 5 | | 1 | Maintenace Item - need approval from Rob |
| | GENERAL NOTE | Rasmussen (Mech) | UV | Mechanical | Replace motor in UV14, UV17, UV22, FCU26, | | 1 | Maintence Items |

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Comments |
|--------|--------------------|---------------------|--------------|---------------|---|------|--|
| B100 | VESTIBULE | Rasmussen (Mech) | | Fire Caulking | Patch hole at relocated valve, fire caulk around pipe - both sides of the wall. | | SL confirmed done |
| B111 | PASSAGE | Rasmussen (Mech) | | Fire caulking | Pipe penetrations not fire caulked | | SL confirmed done |
| B112 | WOMEN | Rasmussen (Mech) | | Fire caulking | Pipe penetrations not fire caulked | | SL confirmed done |
| B113 | MEN | Rasmussen (Mech) | | Fire caulking | Pipe penetrations not fire caulked | | SL confirmed done |
| B150 | TOILET | Rasmussen (Mech) | | Fire caulking | Pipe penetrations not fire caulked | | SL confirmed done |
| D107 | BOILER | Rasmussen (Mech) | | Label | Finish insulating and labeling hydronic piping in mechanical room. | | Insulation at valve was still missing on 9/30. Need additional pipe labels at the wall where the pipes leave the room. |
| | GENERAL NOTE | Rasmussen (Mech) | | Label | AHU and CU labels need installed. | | |
| B120 | BIOLOGICAL SCIENCE | Rasmussen (Mech) | uv | Mechanical | No hot water circulation in UV-18 | | SL confirmed done. Bled out the air. IMEG to confirm. |
| B127 | LIBRARY | CMI (HVAC Controls) | UV-28 | Mechanical | Confirm issue/solution. Maybe a bad transformer. | | Maintenance Issue - scheduled for week of 10/19 |
| B130 | WOMENS | Rasmussen (Mech) | EF | Mechanical | Motor needs replaced in EF-3 | | SL confirmed done |
| C107 | CONCESSION | Rasmussen (Mech) | АНИ | Mechanical | Resheave AHU 7 | | Change Order - Parts on back order. Expected delivery 9/28, installed 9/30- wrong part, new schedule 10/14. |
| D107 | BOILER | Rasmussen (Mech) | Boilers | Mechanical | Additional temperature sensors per RFI 72 | | Waiting on CMI to complete |
| | GENERAL NOTE | Rasmussen (Mech) | AHU | Mechanical | No hot water flow to AHU 1, 2, 3, 5 and 6 | | On-site to review 9/30 |
| | GENERAL NOTE | Rasmussen (Mech) | DOAS | Mechanical | Review DOAS condensate route. Owner stated access panels are blocked by condensate pipe. Reroute condensate pipe. | | · · · · · |
| | GENERAL NOTE | Rasmussen (Mech) | Exposed duct | Mechanical | C118, C122, C130 duct vents need ring to hide tabs. | | |
| | GENERAL NOTE | Rasmussen (Mech) | AHU | Mechanical | Resheave AHU1, 3, 4, and 5 | | SL - Confirm Done. IMEG to confirm |
| | GENERAL NOTE | Rasmussen (Mech) | UV | Mechanical | Replace motor in UV14, UV17, UV22, FCU26, | | Maintenance Items, scheduled for 10/14 |
| B112 | WOMEN | Rasmussen (Mech) | | Plumbing | Sink drain leaking. | | KH to review. |

$\mathbf{W}AIA^{\circ}$ Document G704/CMa^{$\circ}$ – 1992</sup>

Certificate of Substantial Completion Construction Manager-Adviser Edition

PROJECT:

(Name and address) Shenandoah HS Renovations and Addition

TO OWNER: (Name and address) Shenandoah Community School District 304 W Nishna Road Shenandoah, Iowa, 51601

PROJECT NUMBER: 11-16116-20/ **CONTRACT FOR:** General Construction CONTRACT DATE: March 6, 2020

TO CONTRACTOR: (Name and address) Control Management, Inc 8421 N. 29th Street Omaha, NE 68112

OWNER: X

CONSTRUCTION MANAGER: X ARCHITECT: X

CONTRACTOR: X

FIELD:

OTHER:

DATE OF ISSUANCE: September 21, 2020

PROJECT OR DESIGNATED PORTION SHALL INCLUDE:

Bid Package 4.

The Work performed under this Contract has been reviewed and found, to the Construction Manager's and Architect's best knowledge, information and belief, to be substantially complete. Substantial Completion is the stage in the progress of the Work when the Work or designated portion thereof is sufficiently complete in accordance with the Contract Documents so the Owner can occupy or utilize the Work for its intended use. The date of Substantial Completion of the Project or portion thereof designated above is hereby established as August 26, 2020 which is also the date of commencement of applicable warranties required by the Contract Documents, except as stated below:

Warranty

Date of Commencement

August 26, 2020

A list of items to be completed or corrected is attached hereto. The failure to include any items on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

| CARL A. NELSON COMPANY | light dois | 9/24/2020 | |
|---|--|---|-------|
| CONSTRUCTION MANAGER | ВҮ | DATE | |
| DLR Group inc. (an Iowa corporation) | Mike Krok | 9/23/2020 | |
| ARCHITECT | BY | DATE | |
| The Contractor will complete or correct th Substantial Completion. | | hereto within thirty (30) days from the above date of | |
| Control Management, Inc | The ETTy | 9/28/2020 | |
| CONTRACTOR | BY | DATE | |
| The Owner accepts the Work or designated on August 26, 2020 (date). | d portion thereof as substantially com | plete and will assume full possession thereof at | (time |

| Shenandoah Community School District | | |
|---|----|------|
| OWNER | BY | DATE |

AIA Document G704/CMa[™] - 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:47:32 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. **User Notes:** (3B9ADAB3)

(Note--Owner's and Contractor's legal and insurance counsel should determine and review insurance requirements and coverage.)

August 26, 2020

AIA Document G704/CMa[™] – 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:47:32 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. (3B9ADAB3) User Notes:

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Phase | Comments |
|--------|---------------|---------------------|--------------------|------------|--|------|-------|--|
| D107 | BOILER | CMI (HVAC Controls) | | CONTROLS | No communication between Boiler 2 and BAS. Need to add ModBUS connection for Boiler 2 info. | | 1 | IMEG issue. Needs meeting with boiler rep. on 9/14. Boiler Rep still needs to reset. Be back on 9/23. |
| | | | DOAS | | Conduit not secure outside by the DOAS | | 1 | |
| | GENERAL NOTES | CMI (HVAC Controls) | | CONTROLS | No communication between Boiler 2 and BAS. Need to add MosBUS connection for Boiler 2 info. | | 1 | CMI confirmed done. |
| | GENERAL NOTES | CMI (HVAC Controls) | AHUs 1, 2, 3, 5, 6 | CONTROLS | Not working in heating mode. Reasons? | | 1 | Rasmussen Issue? |
| | GENERAL NOTES | CMI (HVAC Controls) | | CONTROLS | Latenancy Issue | | 1 | CMI confirmed done. |
| | GENERAL NOTES | CMI (HVAC Controls) | | CONTROLS | Dehumidification programming - change order | | 1 | CMI confirmed done. |
| B102 | CLASSROOM | СМІ | UV-21 | CONTROLS | Why no fan status? | | 1 | Fan now on BACnet. CMI Confirmed done. |
| B127 | LIBRARY | CMI (HVAC Controls) | UV-28 | Mechanical | Confirm issue/solution. Maybe a bad transformer. | | 1 | Maintenance Issue |
| | GENERAL NOTES | CMI (HVAC Controls) | AHU7 | CONTROLS | Programming for AHU7 Kitchen - change order | | 1 | CO approve on 9/21, Scheduled for 9/24 |
| | GENERAL NOTES | CMI (HVAC Controls) | FCU | Mechanical | FCU31 and FCU37 - Not on-line. Why? | | 1 | CMI confirmed done. |
| | GENERAL NOTES | CMI (HVAC Controls) | FCU | Mechanical | There are a number of maintenance items affecting FCUs that will prevent the units from being operational. FCU-25, FCU-27, AHU-4, FCU-32 Bad economizer actuator. | | 1 | IMEG comment, update CXAlloy - CMI says will fix 9/17 FCU 25, 27, and 32; AHU-4. Fix needs verified. |
| B106 | CONFERENCE | CMI (HVAC Controls) | | Thermostat | Install thermostat in B106. Remove thermostat in B103 per 8/28/2020 email. | | 1 | CMI confirmed done. |

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Comments | | | | |
|--------|---------------|---------------------|-----------------|------------|---|------|--|--|--|--|--|
| B102 | CLASSROOM | СМІ | UV-21 | CONTROLS | Why no fan status? | | Fan now on BACnet. CMI Confirmed done. IMEG to confirm. | | | | |
| | GENERAL NOTES | CMI (HVAC Controls) | | CONTROLS | Latenancy Issue | | CMI confirmed done. IMEG to confirm. | | | | |
| | GENERAL NOTES | CMI (HVAC Controls) | | CONTROLS | Dehumidification programming - change order | | CMI confirmed done. IMEG to confirm. | | | | |
| | GENERAL NOTES | CMI (HVAC Controls) | AHU7 | CONTROLS | Programming for AHU7 Kitchen - change order | | CMI confirmed done. IMEG to confirm. | | | | |
| | GENERAL NOTES | CMI (HVAC Controls) | FCU | Mechanical | FCU31 and FCU37 - Not on-line. Why? | | CMI confirmed done. IMEG to confirm. | | | | |
| | GENERAL NOTES | CMI (HVAC Controls) | AHU6 | Mechanical | AHU6 - needs new actuator. | | CMI confirmed installed, waiting on functional testing results. IMEG to confirm. | | | | |
| | GENERAL NOTES | CMI (HVAC Controls) | FCU | Mechanical | There are a number of maintenance items affecting FCUs that will prevent the units from being operational. FCU-25, FCU-27, AHU-4, FCU-32 Bad economizer actuator. | | IMEG comment, update CXAlloy - CMI says will fix 9/17 FCU 25, 27, and 32; AHU- 4. Fix needs verified by IMEG. | | | | |
| | GENERAL NOTES | CMI (HVAC Controls) | Boiler | CONTROLS | Programming for additional boiler sensor per RFI 72 | | Scheduled for week of 10/19 | | | | |
| | GENERAL NOTES | CMI (HVAC Controls) | AHU 3 and 6 | CONTROLS | Reprogramming for valves installed incorrectly. | | Scheduled for week of 10/19 | | | | |
| | GENERAL NOTES | CMI (HVAC Controls) | AHU 1, 2, and 5 | CONTROLS | Confirm hot water is flowing. | | Scheduled for week of 10/19 | | | | |

MAIA® Document G704/CMa[®] – 1992

Certificate of Substantial Completion Construction Manager-Adviser Edition

PROJECT:

(Name and address) Shenandoah HS Renovations and Addition

TO OWNER: (*Name and address*) Shenandoah Community School District 304 W Nishna Road Shenandoah, Iowa, 51601 PROJECT NUMBER: 11-16116-20/ CONTRACT FOR: General Construction CONTRACT DATE: March 9, 2020

TO CONTRACTOR: (Name and address) Big Sky Enterprises, LLC dba K2 Electric 1405 Bluegrass Road Red Oak, IA 51566 CONSTRUCTION MANAGER: X ARCHITECT: X CONTRACTOR: X FIELD:

OTHER:

1

OWNER: X

DATE OF ISSUANCE: September 21, 2020

PROJECT OR DESIGNATED PORTION SHALL INCLUDE:

Bid Package 5 excluding items for Secure Entrance, Door Access Controls, and Automatic Operators.

The Work performed under this Contract has been reviewed and found, to the Construction Manager's and Architect's best knowledge, information and belief, to be substantially complete. Substantial Completion is the stage in the progress of the Work when the Work or designated portion thereof is sufficiently complete in accordance with the Contract Documents so the Owner can occupy or utilize the Work for its intended use. The date of Substantial Completion of the Project or portion thereof designated above is hereby established as August 26, 2020 which is also the date of commencement of applicable warranties required by the Contract Documents, except as stated below:

Warranty

Date of Commencement

August 26, 2020

A list of items to be completed or corrected is attached hereto. The failure to include any items on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

| CARL A. NELSON COMPANY | Cynt Zors | 9/24/2020 | |
|--|---|---|-------|
| CONSTRUCTION MANAGER | BY | DATE | |
| DLR Group inc. (an Iowa corporation) | Mike Knoe | 9/23/2020 | |
| ARCHITECT | BY | DATE | |
| The Contractor will complete or correct th Substantial Completion. Big Sky Enterprises LLC | e Work on the list of items attached he | reto within thirty (30) days from the above date of | |
| dba K2 Electric | 1 am/n | 10-13-20 | |
| CONTRACTOR | ВҮ | DATE | |
| The Owner accepts the Work or designate on August 26, 2020 (date). | d portion thereof as substantially comp | lete and will assume full possession thereof at | (time |
| Shenandoah Community School District | | | |

OWNER BY

AIA Document G704/CMa[™] – 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:45:45 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes: (3B9ADAB5)

DATE

(Note--Owner's and Contractor's legal and insurance counsel should determine and review insurance requirements and coverage.)

August 26, 2020

AIA Document G704/CMa[™] - 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:45:45 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes: (3B9ADAB5)

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Comments |
|--------|---------------|------------|----------------|----------------------------|---|------|---------------------------|
| C116 | STORAGE | K2 (Elec) | WEST | Cover plate/ Face Plate | needs cover plate | | Locked rm. Couldn't check |
| 006 | Vestibule | K2 (Elec) | | Door | Wiring for auto operator system. | | DH Confirmed |
| A100 | VESTIBULE | K2 (Elec) | West | Door | Wiring for door operators. | | DH Confirmed |
| B100 | VESTIBULE | K2 (Elec) | | Door | Electrical j-boxes for new ADA actuators have not been installed | | DH Confirmed |
| B115 | CORRIDOR | K2 (Elec) | Seating alcove | General | Outlet cover with broken screw. | | Not done 9/9 |
| B119 | HOME EC/FCS | K2 (Elec) | Floor | General | Longer screws to secure floor outlet covers. | | DH Confirmed |
| A100 | VESTIBULE | K2 (Elec) | Ceiling | Light Fixtures | Cover plate for emergency battery test button. | | DH Confirmed |
| C106 | Kitchen | K2 (Elec) | Ceiling | Light Fixtures | Cut into new ceiling tile, the emergency battery back-up check button. | | |
| D100 | BAND ROOM | K2 (Elec) | Ceiling | Light Fixtures | Occupancy Sensor not shutting off lights | | Not done 9/12 |
| | General Notes | K2 (Elec) | General | Light Fixtures | The manufacturer commissioning called out in the submittal is different from the 3rd part commissioning. The Commissioning performed by IMEG is not a substitution for the manufacturer's commissioning. | | IMEG comment. |
| B119 | HOME EC/FCS | K2 (Elec) | Kitchen hood | Power | Install wiring for last kitchen hood. | | DH Confirmed |
| B143 | DATA/COMM | K2 (Elec) | | Power | Properly ground telecom rack per details | | DH Confirmed |
| C109 | DRY STORAGE | K2 (Elec) | | Power | Missing light switch cover. | | DH Confirmed |
| C126 | TRAINING | K2 (Elec) | | Power | Install the key switch contacts, power to mag-locks | | DH Confirmed |
| | General Notes | K2 (Elec) | General | Site | Clean up around light poles | | DH Confirmed |
| B128 | OFFICE | K2 (Elec) | South | Wiremold | Wiremold for data wiring is too short. Add cover by ceiling. | | DH Confirmed |

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Comments |
|--------|---|------------|----------|-----------------------|---|------|-----------------------------|
| B100 | VESTIBULE | K2 (Elec) | | Caulking | Caulk at conduit penetrations at masonry wall | | See item 183 on DLR's punch |
| B100 | VESTIBULE | KZ (EIEC) | | Caulking | Caulk at conduit penetrations at masonry wait | | list. |
| | Vestibule K2 (Elec) Door Wiring for auto operator system. | | | Wood door not opening | | | |
| 006 | | K2 (Elec) | | Door | Wiring for auto operator system. | | smoothly, 9/30. Likely a |
| | | | | | | | Genesis issue. |
| | General Notes | K2 (Elec) | General | | The manufacturer commissioning called out in the submittal is different from the 3rd part commissioning. The Commissioning performed by IMEG is not a substitution for the manufacturer's commissioning. | | IMEG comment. |

MAIA® Document G704/CMa® – 1992

Certificate of Substantial Completion Construction Manager-Adviser Edition

PROJECT:

(Name and address) Shenandoah HS Renovations and Addition

TO OWNER: (*Name and address*) Shenandoah Community School District 304 W Nishna Road Shenandoah, Iowa, 51601 PROJECT NUMBER: 11-16116-20/ CONTRACT FOR: General Construction CONTRACT DATE: March 6, 2020

TO CONTRACTOR: (*Name and address*) Tri-City Electric Company of Iowa 6225 N. Brady Street Davenport, IA 52806 OWNER: X CONSTRUCTION MANAGER: X ARCHITECT: X CONTRACTOR: X FIELD: OTHER:

1

DATE OF ISSUANCE: September 21, 2020

PROJECT OR DESIGNATED PORTION SHALL INCLUDE:

Bid Package 6 excluding items for Secure Entrance, Door Access Controls, and Automatic Operators.

The Work performed under this Contract has been reviewed and found, to the Construction Manager's and Architect's best knowledge, information and belief, to be substantially complete. Substantial Completion is the stage in the progress of the Work when the Work or designated portion thereof is sufficiently complete in accordance with the Contract Documents so the Owner can occupy or utilize the Work for its intended use. The date of Substantial Completion of the Project or portion thereof designated above is hereby established as August 26, 2020 which is also the date of commencement of applicable warranties required by the Contract Documents, except as stated below:

Warranty

Date of Commencement

August 26, 2020

A list of items to be completed or corrected is attached hereto. The failure to include any items on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

| CARL A. NELSON COMPANY | light dors | 9/24/2020 | |
|--|--|---|--------|
| CONSTRUCTION MANAGER | BY | DATE | |
| DLR Group inc. (an Iowa corporation) | Mike Krok | 9/23/2020 | |
| ARCHITECT | BY | DATE | |
| Substantial Completion. | e Work on the list of items attached h | nereto within thirty (30) days from the above date of | |
| Tri-City Electric Company | | 9-25-20 | |
| CONTRACTOR | BY | DATE | |
| The Owner accepts the Work or designate on August 26, 2020 (date). | d portion thereof as substantially com | plete and will assume full possession thereof at | (time) |
| Shenandoah Community School District | | | |
| OWNER | BY | DATE | |
| | | | |

AIA Document G704/CMa[™] – 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:50:07 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes: (3B9ADAAF)

(Note--Owner's and Contractor's legal and insurance counsel should determine and review insurance requirements and coverage.)

August 26, 2020

AIA Document G704/CMa[™] – 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:50:07 ET on 09/23/2020 under Order No.8182007020 which expires on 04/01/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. (3B9ADAAF) User Notes:

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Phase | Comments |
|--------|-----------|-----------------|-------------------|----------|--|------|-------|---|
| C137 | SAFE ROOM | Tri-City (Tech) | South | Camera 🔬 | Patch around security camera (not bypassed). | | 1 | Tri-City confirmed done. |
| 006 | VESTIBULE | Tri-City (Tech) | nfirmed these are | Doors | These doors are getting new automatic operators. There is an existing card reader. We will need your assistance in coordinating the operator and the card reader. K2 will be providing power to operator and door actuator push pads. Feld will need to install low voltage for latch retraction. All hardware is currently on-site, however, operators are going to be installed at the same time as the Secure Entry. | | 1 | Waiting on Genesis, Scheduled for 9/25 |
| A100 | VESTIBULE | Tri-City (Tech) | NCO to verify. | Doors | Three pairs of doors are getting new card readers. Two pairs of doors are getting new operators. One pair of doors have new electrified panics, only. Feld will need to do low voltage for card readers, latch retractions, and coordination of operators, card readers, and timing for door open and close. | | 1 | Waiting on Genesis, Scheduled for 9/25 |
| B100 | VESTIBULE | Tri-City (Tech) | | Doors | These doors have an existing card reader, but are getting new auto operators. Feld will need to do camera, door unlock button, low voltage card reader and latch retraction, coordination of card readers and operators. Latch retraction timing for lock and unlock. Install camera, door unlock, card reader, operators and low voltage wiring | | 1 | Done except for download program for door buzzer, and disabling door operator when doors are locked. Work scheduled for 9/25. |
| C126 | TRAINING | Tri-City (Tech) | | Doors | Connect mag locks to fire alarm | | 1 | Waiting on Genesis, Scheduled for 9/25 |

MAIA® Document G706A – 1994

Contractor's Affidavit of Release of Liens

| PROJECT: (Name and address) | ARCHITECT'S PROJECT NUMBER: | OWNER: 🔀 |
|------------------------------------|--|---------------|
| Shenandoah Community School | 11-16116-20 / 19-023 | ARCHITECT: 🔀 |
| District | | |
| Shenandoah High School Renovations | CONTRACT FOR: Bid Package No. 7 - | CONTRACTOR: 🔀 |
| - Asbestos Abatement | Asbestos Abatement | SURETY: |
| 1000 Mustang Drive | | |
| Shenandoah, IA 51601 | | OTHER: 🗌 |
| TO OWNER: (Name and address) | CONTRACT DATED: February 24, 2020 | |
| Shenandoah Community School | | |
| District | | |
| 304 West Nishna Road | | |
| Shenandoah, IA 51601 | | |

STATE OF: Iowa COUNTY OF: Douglas

The undersigned hereby certifies that to the best of the undersigned's knowledge, information and belief, except as listed below, the Releases or Waivers of Lien attached hereto include the Contractor, all Subcontractors, all suppliers of materials and equipment, and all performers of Work, labor or services who have or may have liens or encumbrances or the right to assert liens or encumbrances against any property of the Owner arising in any manner out of the performance of the Contract referenced above.

EXCEPTIONS:

 SUPPORTING DOCUMENTS ATTACHED HERETO:
 Contractor's Release or Waiver of Liens, conditional upon receipt of final payment.

2. Separate Releases or Waivers of Liens from Subcontractors and material and equipment suppliers, to the extent required by the Owner, accompanied by a list thereof. **CONTRACTOR:** *(Name and address)* McGill Asbestos Abatement, LLC 4205 South 33rd Street Omaha, NE 68107

BY:

(Signature of authorized representative)

GIREG JOHNSONS, PRESIDENT (Printed name and title)

Subscribed and sworn to before me on this date: [0 - 3 - 20]

Notary Public: Jan A. Jh My Commission Expires: M., 31, 2011

> State of Nebraska – General Notary JAMES F. LYNCH My Commission Expires May 31, 2022

> > 1

AIA Document G706A[™] – 1994. Copyright © 1982 and 1994 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 11:09:52 ET on 08/20/2020 under Order No.1977618712 which expires on 04/23/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes: (3B9ADA75)

AIA[®] Document G706[®] – 1994

Contractor's Affidavit of Payment of Debts and Claims

| PROJECT: (Name and address) | ARCHITECT'S PROJECT NUMBER: | OWNER: 🖂 |
|------------------------------------|--|---------------|
| Shenandoah Community School | 11-16116-20 / 19-023 | ARCHITECT: 🔀 |
| District | | CONTRACTOR: 🔀 |
| Shenandoah High School | CONTRACT FOR: Bid Package No. 7 - | SURETY: 🔀 |
| Renovations - Asbestos Abatement | Asbestos Abatement | OTHER: |
| 1000 Mustang Drive | | |
| Shenandoah, IA 51601 | | |
| TO OWNER: (Name and address) | CONTRACT DATED: February 24, 2020 | |
| Shenandoah Community School | | |
| District | | |
| 304 West Nishna Road | | |
| Shenandoah, IA 51601 | | |
| | | |
| STATE OF: JOWA | | |

COUNTY OF: Douglas

The undersigned hereby certifies that, except as listed below, payment has been made in full and all obligations have otherwise been satisfied for all materials and equipment furnished, for all work, labor, and services performed, and for all known indebtedness and claims against the Contractor for damages arising in any manner in connection with the performance of the Contract referenced above for which the Owner or Owner's property might in any way be held responsible or encumbered.

EXCEPTIONS:

SUPPORTING DOCUMENTS ATTACHED HERETO:

 Consent of Surety to Final Payment. Whenever Surety is involved, Consent of Surety is required. AIA Document G707, Consent of Surety, may be used for this purpose
 Indicate Attachment X Yes No

The following supporting documents should be attached hereto if required by the Owner:

1. Contractor's Release or Waiver of Liens, conditional upon receipt of final payment.

2. Separate Releases or Waivers of Liens from Subcontractors and material and equipment suppliers, to the extent required by the Owner, accompanied by a list thereof.

3. Contractor's Affidavit of Release of Liens (AIA Document G706A).

CONTRACTOR: (*Name and address*) McGill Asbestos Abatement, LLC 4205 South 33rd Street Omaha, NE 68107

BY:

(Signature of authorized representative)

GREG JOHNSON, (Printed name and title)

Subscribed and sworn to before me on this date: 10 - 8 - 20

1

Notary Public: My Commission Expires: May 31, 2022

F. LA

State of Nebraska – General Notary JAMES F. LYNCH My Commission Expires May 31, 2022

AIA Document G706[™] – 1994. Copyright © 1970 and 1994 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 11:08:09 ET on 08/20/2020 under Order No.1977618712 which expires on 04/23/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents[®] Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes: (3B9ADA65)

AIA° Document G704/CMa^{$\circ}$ – 1992</sup>

Certificate of Substantial Completion Construction Manager-Adviser Edition

PROJECT: (Name and address) Shenandoah Community School District Shenandoah High School Renovations 1000 Mustang Drive Shenandoah, IA 51601 TO OWNER: (Name and address) Shenandoah Community School District 304 West Nishna Road Shenandoah, IA 51601

DATE OF ISSUANCE: October 7, 2020

PROJECT OR DESIGNATED PORTION SHALL INCLUDE:

Shenandoah High School Renovation - Phase 2

PROJECT NUMBER: 11-16116-20 / 19-023 CONTRACT FOR: Bid Package No. 7 -Asbestos Abatement CONTRACT DATE: February 24, 2020 TO CONTRACTOR:

(Name and address) McGill Asbestos Abatement, LLC 4205 South 33rd Street Omaha, NE 68107

CONSTRUCTION MANAGER: ARCHITECT: CONTRACTOR: FIELD: OTHER:

OWNER: 🛛

The Work performed under this Contract has been reviewed and found, to the Construction Manager's and Architect's best knowledge, information and belief, to be substantially complete. Substantial Completion is the stage in the progress of the Work when the Work or designated portion thereof is sufficiently complete in accordance with the Contract Documents so the Owner can occupy or utilize the Work for its intended use. The date of Substantial Completion of the Project or portion thereof designated above is hereby established as this certificate which is also the date of commencement of applicable warranties required by the Contract Documents, except as stated below:

Warranty August 26, 2020 Date of Commencement August 26, 2020

A list of items to be completed or corrected is attached hereto. The failure to include any items on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

Carl A. Nelson & Company CONSTRUCTION MANAGER

Carl A. Nelson & Company ARCHITECT

EMM Mcculles

- <u>10/7/2020</u> 10/7/2020

The Contractor will complete or correct the Work on the list of items attached hereto within 30 days from the above date of Substantial Completion.

McGill Asbestos Abatement, LLC CONTRACTOR

| an | |
|----|--|
| | |
| BY | |

______ <u>/0 / 7 / 2020</u> DATE


The Owner accepts the Work or designated portion thereof as substantially complete and will assume full possession thereof at 8:00 a.m. (time) on August 26, 2020 (date).

| Shenandoah Community School | | |
|-----------------------------|----|------|
| District | | |
| OWNER | ВҮ | DATE |

AIA Document G704/CMa1" - 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA." the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 15:10:30 ET on 10/07/2020 under Order No.1977618712 which expires on 04/23/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents® Terms of Service. To report copyright violations, e-mail copyright@aia.org. **User Notes:**

(Note--Owner's and Contractor's legal and insurance counsel should determine and review insurance requirements and coverage.)

Per contract documents.



AIA Document G704/CMa – 1992

Certificate of Substantial Completion Construction Manager-Adviser Edition

PROJECT:

(Name and address) Shenandoah Community School District Shenandoah High School Renovations 1000 Mustang Drive Shenandoah, IA 51601

TO OWNER: (Name and address) Shenandoah Community School District 304 West Nishna Road Shenandoah, IA 51601 PROJECT NUMBER: 11-16116-20 / 19-023 CONTRACT FOR: Bid Package No. 8 -Finishes and Pavement CONTRACT DATE: March 9, 2020 TO CONTRACTOR:

(Name and address) Genesis Contracting Group, LLC 404 Hill Street Lincoln, NE 68502 CONSTRUCTION MANAGER: ARCHITECT: CONTRACTOR: FIELD: CONTRACTOR: CO

OWNER: 🕅

DATE OF ISSUANCE: September 21, 2020

PROJECT OR DESIGNATED PORTION SHALL INCLUDE:

Shenandoah High School Renovation - Phase 2 See attached Punch List for remaining items.

The Work performed under this Contract has been reviewed and found, to the Construction Manager's and Architect's best knowledge, information and belief, to be substantially complete. Substantial Completion is the stage in the progress of the Work when the Work or designated portion thereof is sufficiently complete in accordance with the Contract Documents so the Owner can occupy or utilize the Work for its intended use. The date of Substantial Completion of the Project or portion thereof designated above is hereby established as this certificate which is also the date of commencement of applicable warranties required by the Contract Documents, except as stated below:

Warranty

August 26, 2020

Date of Commencement August 26, 2020

A list of items to be completed or corrected is attached hereto. The failure to include any items on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

| Carl A. Nelson & Company | ant Dars | 9/21/2020 |
|--|--|---|
| CONSTRUCTION MANAGER | BY | DATE |
| Carl A. Nelson & Company | Eller Mcculles | 8/21/2020 |
| ARCHITECT | BY | DATE |
| The Contractor will complete or correct or c | et the Work on the list of items attached hereto | within 30 days from the above date of Substantial |

Genesis Contracting Group, LLC CONTRACTOR
BY
DATE

The Owner accepts the Work or designated portion thereof as substantially complete and will assume full possession thereof at 8:00 a.m. (time) on August 26, 2020 (date).

| Shenandoah Community School | | |
|-----------------------------|----|------|
| District | | |
| OWNER | ВҮ | DATE |

AiA Document G704/CMa^{TV} – 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA." the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 16:21:21 ET on 09/18/2020 under Order No.1977618712 which expires on 04/23/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents[®] Terms of Service. To report copyright violations, e-mail copyright@aia.org.

(Note--Owner's and Contractor's legal and insurance counsel should determine and review insurance requirements and coverage.)

Per contract documents.

AIA Document G704/CMa[®] – 1992. Copyright © 1992 by The American Institute of Architects. All rights reserved. The "American Institute of Architects," "AIA," the AIA Logo, and "AIA Contract Documents" are registered trademarks and may not be used without permission. This document was produced by AIA software at 16:21:21 ET on 09/18/2020 under Order No.1977618712 which expires on 04/23/2021, is not for resale, is licensed for one-time use only, and may only be used in accordance with the AIA Contract Documents[®] Terms of Service. To report copyright violations, e-mail copyright@aia.org. User Notes:

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Phase | Comments |
|--------|------------------------|--------------|----------------------------|------------|--|------|-------|---|
| B119 | HOME EC/FCS | Genesis (GC) | FCS island west | Casework | cabinet north of stove was supposed to have roll out shelves. Refer to 7/A2.2 | | 2 | See also 9/A10.2 |
| B119 | HOME EC/FCS | Genesis (GC) | all | Casework | Adjust magnetic closers so the cabinets stay closed. Indicated by blue tape in top corner of cabinet | | 2 | |
| B119 | HOME EC/FCS | Genesis (GC) | all roll out base cabinets | Casework | roll out shelves hit doors when trying to roll them out | | 2 | |
| B119 | HOME EC/FCS | Genesis (GC) | all roll out base cabinets | Casework | shelves were to have a vertical piece on the front of shelf, same height as the vertical pieces to the side, as shown on 9/A10.2 | | 2 | |
| B119 | HOME EC/FCS | Genesis (GC) | all | Casework | large gaps between cabinet doors | | 2 | Owner review - Not Accepted. Doors need replaced. |
| B119 | HOME EC/FCS | Genesis (GC) | FCS island east and south | Casework | repair scratches on tall cabinets | | 2 | Cabinets being replaced due to pegs not in alignment |
| D124 | SPECIAL ED KITCHENETTE | Genesis (GC) | | Casework | casework door at sink - Missing magnets | | 2 | Not done 9/30 |
| B115 | CORRIDOR | Genesis (GC) | B102A | Door | install hold open | | 2 | |
| B146 | CLASSROOM | Genesis (GC) | B146B | Door | Remove old door stop | | 2 | |
| C117 | СОАСН | Genesis (GC) | C117A | Door | Lever installed too low. | | 2 | |
| C123 | EQUIPMENT | Genesis (GC) | C123A | Door | Lever installed too low. | | 2 | |
| C127 | СОАСН | Genesis (GC) | C127B | Door | Lever installed too low. | | 2 | |
| | General Notes | Genesis (GC) | | Door | Jason to provide 50 blank keys -and key code- spreadsheet to Rob. | | 2 | Key code spreadsheet given to Rob. |
| A101 | LOBBY | Genesis (GC) | near east exterior doors | Dry Waller | Needs skim coated. | | 2 | Not done 9/30 |
| A101 | LOBBY | Genesis (GC) | Wall A102A is located on | Dry Waller | redo area around control joint. Unacceptable craftsmanship with skim coat. | | 2 | Not done 9/30 |
| A101 | LOBBY | Genesis (GC) | Wall A104A is located on | Dry Waller | redo area around control joint. Unacceptable craftsmanship with skim coat. | | 2 | Not done 9/30 |
| A101 | LOBBY | Genesis (GC) | Wall A104A is located on | Dry Waller | skim coat wall. Unacceptable craftsmanship | | 2 | Not done 9/30 |
| A102 | VESTIBULE | Genesis (GC) | west | Dry Waller | repair GWB around panel and light switch. | | 2 | Not done 9/30 |
| A100 | VESTIBULE | Genesis (GC) | A100B | Flooring | Add transition strip to clean up carpet edge on the school side of the threshold. | | 2 | Not done 9/30 |
| A107 | AUDITORIUM | Genesis (GC) | Stage steps | Flooring | Fix transiton between stage and top step. At south stair, remove pencil mark and adhesive. | | 2 | pencil still visible on wall - Review for pencil mark 9/18 |

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Phase | Comments |
|--------|-------------------|--------------|--|----------|--|------|-------|--|
| A109 | VESTIBULE | Genesis (GC) | stairs | Flooring | risers need termination strip | | 2 | Not accepted, 9/30 |
| B100 | VESTIBULE | Genesis (GC) | | Flooring | New walk-off carpet not installed. | | 2 | Owner review, not installed per plans |
| B109 | NURSE | Genesis (GC) | floor at door into bathroom | Flooring | reinstall LVT to trim better around door frame or caulk? | | 2 | Not done 9/30 |
| B119 | HOME EC/FCS | Genesis (GC) | ISL2 West | Flooring | 2 holes in flooring. Patch or replace tiles | | 2 | Replace the tile that is not under the island. |
| B119 | HOME EC/FCS | Genesis (GC) | east side of west UV | flooring | gap in flooring at unit ventilator. Reinstall tiles to remove gap | | 2 | Repair using grey vinyl patch |
| B119 | HOME EC/FCS | Genesis (GC) | east wall, adjacent to cabinets, northern half | Flooring | fill gap in LVT flooring or replace tiles, multiple locations | | 2 | Repair using grey vinyl patch |
| C100 | VESTIBULE | Genesis (GC) | Multiple Walls | Flooring | Red wall base not installed per change order. Install when material is available. | | 2 | Base coming loose on 9/30 |
| C133 | ICE MACHINE | Genesis (GC) | Floor | Flooring | Missing LVT and transition strip. Clean transition strip. | | 2 | Not done 9/30 |
| C135 | VESTIBULE | Genesis (GC) | west, both sides of doors into C144 | flooring | gap in flooring at both sides of doors. Replace current carpet tile that is properly cut to infill gap. | | 2 | Right hand side of door into storage needs a little more caulk |
| D100 | BAND ROOM | Genesis (GC) | east | Flooring | install carpet on counter. Nosing not installed. | | 2 | Not done 9/30 |
| D126 | CORRIDOR | Genesis (GC) | NW | Flooring | fix gap between carpet and base. Glue/replace tile. | | 2 | GH Confirmed Done |
| B133 | OFFICE | Genesis (GC) | West | General | Missing screws in light switch cover plate | | 2 | 2 screws max |
| B137 | CLASSROOM | Genesis (GC) | B137A | Glazing | Door lite scratched. | | 2 | Not done 9/9 |
| C117 | СОАСН | Genesis (GC) | C117B | Glazing | Door lite scratched. | | 2 | Not done 9/10 |
| A102 | VESTIBULE | Genesis (GC) | west | Paint | touch up multiple locations near panel | | 2 | N/C |
| A104 | VESTIBULE | Genesis (GC) | ceiling | Paint | paint, cut in better, remove staining | | 2 | N/C |
| A107 | AUDITORIUM | Genesis (GC) | A107D | Paint | Door frame paint peeling. Sand and repaint. Cut in | | 2 | Not done 9/9 |
| A109 | VESTIBULE | Genesis (GC) | | Paint | Existing CMU wall, patch hole and paint to match adjacent | | 2 | N/C |
| C110 | GYMNASIUM | Genesis (GC) | South | Paint | Outlet cover not installed | | 2 | N/C |
| C118 | GIRLS LOCKER ROOM | Genesis (GC) | C118A | Paint | Paint door and frame. | | 2 | |
| | GENERAL NOTE | Genesis (GC) | | Paint | Reinstall covers over closers on HM doors; A107E, A109A (1 cover), A118A, B131A, C107A, C109B, D100A, and D108A. | | 2 | According to 3D scan majority of closer covers were in place at start of project. |
| B119 | HOME EC/FCS | Genesis (GC) | All pull stations | Tile | remove and reinstall tile at pull station to eliminate gap | | 2 | |
| B119 | HOME EC/FCS | Genesis (GC) | FCS island west | Tile | tile to extend behind stove. Reference ASI 1 41/A0.0 | | 2 | Need more red tile. |

| NUMBER | NAME | Contractor | Location | Item | Description | Done | Phase | Comments |
|--------|---------------|--------------|--|----------|--|------|-------|--|
| B119 | HOME EC/FCS | Genesis (GC) | FCS island west | Casework | cabinet north of stove was supposed to have roll out shelves. Refer to 7/A2.2 | | 2 | See also 9/A10.2 |
| B119 | HOME EC/FCS | Genesis (GC) | all | Casework | Adjust magnetic closers so the cabinets stay closed. Indicated by blue tape in top corner of cabinet. | | 2 | Tall cabinets close to teacher's desk. |
| B119 | HOME EC/FCS | Genesis (GC) | all roll out base cabinets | Casework | roll out shelves hit doors when trying to roll them out | | 2 | |
| B119 | HOME EC/FCS | Genesis (GC) | all roll out base cabinets | Casework | shelves were to have a vertical piece on the front of shelf, same height as the vertical pieces to the side, as shown on 9/A10.2 | | 2 | |
| B119 | HOME EC/FCS | Genesis (GC) | all | Casework | large gaps between cabinet doors | | 2 | Owner review - Not Accepted. Doors need replaced or adjusted to reduce gap. |
| B119 | HOME EC/FCS | Genesis (GC) | FCS island east and south | Casework | repair scratches on tall cabinets | | 2 | Cabinets being replaced due to pegs not in alignment |
| C109 | DRY STORAGE | Genesis (GC) | C109B | Door | Door lock not working. | | 2 | |
| C117 | СОАСН | Genesis (GC) | C117A | Door | Lever installed too low. | | 2 | |
| C123 | EQUIPMENT | Genesis (GC) | C123A | Door | Lever installed too low. | | 2 | |
| C127 | СОАСН | Genesis (GC) | C127B | Door | Lever installed too low. | | 2 | |
| | General Notes | Genesis (GC) | | Door | Jason to provide 50 blank keys- and key code- spreadsheet to Rob. | | 2 | Key code spreadsheet given to Rob. |
| A100 | VESTIBULE | Genesis (GC) | A100B | Flooring | Add transition strip to clean up carpet edge on the school side of the threshold. | | 2 | Not done 9/30 |
| A109 | VESTIBULE | Genesis (GC) | stairs | Flooring | risers need termination strip | | 2 | Not accepted, 9/30 |
| B109 | NURSE | Genesis (GC) | floor at door into bathroom | Flooring | reinstall LVT to trim better around door frame or caulk? | | 2 | Not done 9/30 |
| B119 | HOME EC/FCS | Genesis (GC) | east wall, adjacent to cabinets, northern half | Flooring | fill gap in LVT flooring or replace tiles, multiple locations | | 2 | Repair using grey vinyl patch |
| C100 | VESTIBULE | Genesis (GC) | Multiple Walls | Flooring | Red wall base not installed per change order. Install when material is available. | | 2 | Base coming loose on 9/30 |
| C135 | VESTIBULE | Genesis (GC) | west, both sides of doors into C144 | flooring | gap in flooring base at both sides of doors Replace- current carpet tile that is properly cut to infill gap. | | 2 | Right hand side of door into storage. |
| D100 | BAND ROOM | Genesis (GC) | east | Flooring | install carpet on counter. Nosing not installed. | | 2 | Not done 9/30 |
| B137 | CLASSROOM | Genesis (GC) | B137A | Glazing | Door lite scratched. | | 2 | Not done 9/9 |
| C117 | СОАСН | Genesis (GC) | C117B | Glazing | Door lite scratched. | | 2 | Not done 9/10 |
| | GENERAL NOTE | Genesis (GC) | | Paint | Reinstall covers over closers on HM doors; A107E, A109A (1 cover), A118A, B131A, C107A, C109B, D100A, and D108A. | | 2 | According to 3D scan majority of closer covers were in place at start of project. |
| B119 | HOME EC/FCS | Genesis (GC) | All pull stations | Tile | remove and reinstall tile at pull station to eliminate gap | | 2 | Not done 10/07 |
| B119 | HOME EC/FCS | Genesis (GC) | FCS island west | Tile | tile to extend behind stove. Reference ASI 1 41/A0.0 | | 2 | Need more red tile. |